1. External Photograph of EUT

Brand Name: INQ / Model Name: T2-218U

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 1 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 2 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 3 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 4 of 27 Report Issued Date : Mar. 28, 2011

Report Version : Rev. 02

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 5 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 6 of 27 Report Issued Date : Mar. 28, 2011 Report Version : Rev. 02

2. Photograph of Accessory

Brand Name: INQ / Model Name: T2-218U

Report No.: EP092959

List of Accessory:

| List of Addessory. | | |
|----------------------------|------------|-------------------|
| Specification of Accessory | | |
| AC Adapter | Brand Name | INQ |
| | Model Name | HS-050040U5 |
| Battery | Brand Name | INQ |
| | Model Name | WB5 |
| Earphone | Brand Name | minami |
| | Model Name | ME-812A |
| USB Cable | Brand Name | EASON |
| | Model Name | UX004SX005-S8315 |
| LCD Panel | Brand Name | BYD |
| | Model Name | BM320480-8660FTGH |
| Camera | Brand Name | BYD |
| | Model Name | BOCP9P111-MIC8012 |
| TP Module | Brand Name | BYD |
| | Model Name | TP-2C-DZ-10460AB |

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 7 of 27
Report Issued Date : Mar. 28, 2011

Report Version : Rev. 02



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 8 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 9 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 10 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 11 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

SPORTON LAB. Photographs of EUT


Brand Name: INQ / Model Name: T2-218U

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 12 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 13 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02



Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 14 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 15 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 16 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 17 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02