3. Internal Photograph of EUT


Brand Name: INQ / Model Name: T2-218U

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 18 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 19 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 20 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 21 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 22 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 23 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 24 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 25 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 26 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02

Report No.: EP092959



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : 27 of 27
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 02