

## Appendix D. Product Photos




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : D1 of D2
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 03

Report No.: FA092959A



## **Antenna Location:**



Antenna location	Antenna Distance (cm)
WWAN Antenna to WLAN & Bluetooth Antenna	0.4

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : D2 of D2
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 03

Report No.: FA092959A



Report No.: FA092959A

## Appendix E. Test Setup Photos





**Right Cheek** 

Right Tilted





Left Cheek

Left Tilted

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : E1 of E3
Report Issued Date : Mar. 28, 2011

Report Version : Rev. 03





Rear Face of the DUT with Phantom 1 cm Gap (EUT without Earphone)




Report No.: FA092959A


Rear Face of the DUT with Phantom 1 cm Gap (EUT with Earphone)




Front Face of the DUT with Phantom 1 cm Gap (EUT without Earphone)



Front Face of the DUT with Phantom 1 cm Gap (EUT with Earphone)



Left Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : E2 of E3 Report Issued Date: Mar. 28, 2011 Report Version : Rev. 03





Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZEN0020241907 Page Number : E3 of E3
Report Issued Date : Mar. 28, 2011
Report Version : Rev. 03

Report No.: FA092959A