



## 1 Internal Photos of the EUT



Internal view

Antenna



Place of the PCB1



Place of the PCB2

opyright of this report is owned by Centre of Testing Service and may not be reproduced other than in full except with the written approval of the issuing Company.

## CENTRE OF TESTING SERVICE CO., LTD.

Building F, Dachuang industrial park, No.379, Zhongshan Dadao, Guangzhou, China Tel: +86-20-85543113 (32 lines) Fax: +86-20-38780406

Complaint line: +86-20-85533471 E-mail: cts@cts-lab.com.cn See Reverse For Terms And Conditions of Service







PCB1 layout

Antenna



PCB1 solder



PCB2 layout

opyright of this report is owned by Centre of Testing Service and may not be reproduced other than in full except with the written approval of the issuing Company.

## CENTRE OF TESTING SERVICE CO., LTD.


Building F, Dachuang industrial park, No.379, Zhongshan Dadao, Guangzhou, China Tel: +86-20-85543113 (32 lines) Fax: +86-20-38780406 Complaint line: +86-20-85533471 E-mail: cts@cts-lab.com.cn

-85533471 E-mail: cts@cts-lab.com.cn See Reverse For Terms And Conditions of Service

## **CENTRE OF TESTING SERVICE**







PCB2 solder

opyright of this report is owned by Centre of Testing Service and may not be reproduced other than in full except with the written approval of the issuing Company.

Building F, Dachuang industrial park, No.379, Zhongshan Dadao, Guangzhou, China Tel: +86-20-85543113 (32 lines) Fax: +86-20-38780406

Complaint line: +86-20-85533471 E-mail: cts@cts-lab.com.cn

See Reverse For Terms And Conditions of Service