





Report no. ETLE110408.0278, Page D1 of D26





Report no. ETLE110408.0278, Page D2 of D26





Report no. ETLE110408.0278, Page D3 of D26






Report no. ETLE110408.0278, Page D4 of D26




Top side view of main board



Report no. ETLE110408.0278, Page D5 of D26




Bottom side view of main board



Report no. ETLE110408.0278, Page D6 of D26



Top side view of RF board



Report no. ETLE110408.0278, Page D7 of D26




Bottom side view of RF board



Report no. ETLE110408.0278, Page D8 of D26




Top side view of LCD board



Report no. ETLE110408.0278, Page D9 of D26



Bottom side view of LCD board



Report no. ETLE110408.0278, Page D10 of D26




Top side view of sensor board



Report no. ETLE110408.0278, Page D11 of D26



Bottom side view of sensor board



Report no. ETLE110408.0278, Page D12 of D26



View of LCD panel





Report no. ETLE110408.0278, Page D13 of D26



View of LCD panel label






Top side view of iris recognition camera main board



Report no. ETLE110408.0278, Page D15 of D26



Bottom side view of iris recognition camera main board



Report no. ETLE110408.0278, Page D16 of D26




Top side view of iris recognition camera sub main board



Report no. ETLE110408.0278, Page D17 of D26



Bottom side view of iris recognition camera sub main board



Report no. ETLE110408.0278, Page D18 of D26



Top side view of iris recognition camera motor switch board 1



Report no. ETLE110408.0278, Page D19 of D26



Bottom side view of iris recognition camera motor switch board 1



Report no. ETLE110408.0278, Page D20 of D26




Top side view of iris recognition camera motor switch board 2



Report no. ETLE110408.0278, Page D21 of D26




Bottom side view of iris recognition camera motor switch board 2



Report no. ETLE110408.0278, Page D22 of D26




Top side view of iris recognition camera module



Report no. ETLE110408.0278, Page D23 of D26



Bottom side view of iris recognition camera module



Report no. ETLE110408.0278, Page D24 of D26



View of iris recognition motor





Report no. ETLE110408.0278, Page D25 of D26



View of iris recognition motor label

