


## Appendix E. Setup Photographs

# <Conducted Emission> Mode 2





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : E1 of E2
Report Issued Date Jul. 06, 2018
Report Version : Rev. 01

Report No.: FR850804-02A

Report Template No.: BU5-FR15CBT Version 2.0



### Report No.: FR850804-02A

### <Radiated Emission>

#### **Z** Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : E2 of E2
Report Issued Date Jul. 06, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0