

## Appendix A. Setup Photographs

## <Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 Page Number : A1 of A2
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: FR552956D

Report Template No.: BU5-FR15CNFC Version 1.0




## <Radiated Emission>

Y Plane

9 kHz~30MHz



30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 Page Number : A2 of A2
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: FR552956D

Report Template No.: BU5-FR15CNFC Version 1.0