3. Internal Photograph of EUT

Brand Name: CAT / Model Name: S40 / Marketing Name: S40

Report No.: EP552956




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 9 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: EP552956




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 10 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Brand Name: CAT / Model Name: S40 / Marketing Name: S40




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 11 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: EP552956




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 12 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Brand Name: CAT / Model Name: S40 / Marketing Name: S40




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 13 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: EP552956




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 14 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: EP552956




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 15 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: EP552956




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 16 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: EP552956




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 17 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: EP552956




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 18 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: EP552956





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 19 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Brand Name: CAT / Model Name: S40 / Marketing Name: S40




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 20 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 21 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 22 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01




Report No.: EP552956




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 23 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: EP552956




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 24 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: EP552956




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 25 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: EP552956




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 26 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Brand Name: CAT / Model Name: S40 / Marketing Name: S40




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 27 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Brand Name: CAT / Model Name: S40 / Marketing Name: S40





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 28 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 29 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40 Page Number : 30 of 31
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01



Report No.: EP552956



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 IC: 11151A-S40

Page Number : 31 of 31 Report Issued Date : Jul. 16, 2015 Report Version : Rev. 01