


### Report No. : FR7N1019-02D

# Appendix D. Setup Photographs

## <Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZL5AP01 Page Number : D1 of D2
Report Issued Date : Jun. 19, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 2.0




### Report No.: FR7N1019-02D

## <Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZL5AP01 Page Number : D2 of D2
Report Issued Date : Jun. 19, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 2.0