


Report No.: FR850804-02D

Appendix D. Setup Photographs

<Conducted Emission>





TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : D1 of D2
Report Issued Date : Jul. 06, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 2.0



Report No.: FR850804-02D

<Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : D2 of D2
Report Issued Date : Jul. 06, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 2.0