


Appendix B. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5B15AWS Page Number : B1 of B2
Report Issued Date : Jul. 18, 2013
Report Version : Rev. 01

Report No.: FR2D2653-01B




<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5B15AWS Page Number : B2 of B2
Report Issued Date : Jul. 18, 2013
Report Version : Rev. 01

Report No.: FR2D2653-01B