

Report No. : FA2D2653-01

Appendix D. SAR Test Setup Photos





Right Cheek


Right Tilted






Left Cheek

Left Tilted





Back, Test Separation 1 cm

mulanhadaal

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5B15AWS Page Number : D1 of D2 Report Issued Date: Jul. 04, 2013 Report Version : Rev. 01





Report No. : FA2D2653-01

Back with headset, Test Separation 1 cm


Bottom, Test Separation 1 cm







Left Side, Test Separation 1 cm



Right Side, Test Separation 1 cm

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5B15AWS Page Number : D2 of D2
Report Issued Date : Jul. 04, 2013
Report Version : Rev. 01