


Report No.: FR730704E

Appendix D. Setup Photographs

<Conducted Emission> Mode 1





Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZL5EKTRA


: D1 of D2 Page Number Report Issued Date : Apr. 14, 2017 Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC Version 2.0


<Radiated Emission>

Y Plane

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZL5EKTRA Page Number : D2 of D2
Report Issued Date : Apr. 14, 2017
Report Version : Rev. 01

Report No.: FR730704E

Report Template No.: BU5-FR15EWLAC Version 2.0