


Appendix A. Setup Photographs

<Conducted Emission> <Original>



<Terminal>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S60 Page Number : A1 of A2
Report Issued Date : Jun. 06, 2016
Report Version : Rev. 01

Report No.: FR630110-01D


Report Template No.: BU5-FR15CNFC Version 1.0




<Radiated Emission>

X Plane

From 9 kHz~30MHz



From 30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S60 Page Number : A2 of A2
Report Issued Date : Jun. 06, 2016
Report Version : Rev. 01

Report No.: FR630110-01D

Report Template No.: BU5-FR15CNFC Version 1.0