

## Appendix B. Setup Photographs

## <Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S30 Page Number : B1 of B2
Report Issued Date : Aug. 11, 2015
Report Version : Rev. 01

Report No.: FR570160B


Report Template No.: BU5-FR15CBT4.0 Version 1.0



Report No.: FR570160B

## <Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S30 Page Number : B2 of B2
Report Issued Date : Aug. 11, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.0