
## Appendix A. Setup Photographs

## <Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S50 Page Number : A1 of A2
Report Issued Date : Aug. 19, 2014
Report Version : Rev. 01

Report No.: FR463004A

Report Template No.: BU5-FR15CBT Version 1.0


## <Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S50 Page Number : A2 of A2
Report Issued Date : Aug. 19, 2014
Report Version : Rev. 01

Report No.: FR463004A

Report Template No.: BU5-FR15CBT Version 1.0