


Report No.: FR730704A

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID : ZL5EKTRA

Page Number : B1 of B2 Report Issued Date : Apr. 14, 2017 Report Version : Rev. 01


Report Template No.: BU5-FR15CBT Version 2.0




<Radiated Emission>

X Plane

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZL5EKTRA Page Number : B2 of B2
Report Issued Date : Apr. 14, 2017
Report Version : Rev. 01

Report No.: FR730704A

Report Template No.: BU5-FR15CBT Version 2.0