LTE Band 7

Peak-to-Average Ratio

Mode					
Mod.	QP	SK	16C	Limit: 13dB	
RB Size	1RB	Full RB	1RB	Full RB	Result
Lowest CH	4.12	4.84	4.93	5.83	
Middle CH	4.12	4.96	5.13	6.03	PASS
Highest CH	3.74	4.81	4.55	5.71	


Report No.: FG552956B


SPORTON INTERNATIONAL INC. Page Number: A7-1 of 39

TEL: 886-3-327-3456

FAX: 886-3-328-4978

Report Template No.: BU5-FGLTE Version 1.3





26dB Bandwidth

Mode	LTE Band 7 : 26dB BW(MHz)											
BW	1.4MHz		3MHz		5MHz		10MHz		15MHz		20MHz	
Mod.	QPSK	16QAM	QPSK	16QAM	QPSK	16QAM	QPSK	16QAM	QPSK	16QAM	QPSK	16QAM
Lowest CH	-	-	1	-	5.04	5.04	9.97	9.91	14.63	14.87	20.42	20.26
Middle CH	-	-	-	-	5.04	5.06	10.03	9.91	14.6	14.66	20.38	20.46
Highest CH	-	-	-	-	5.04	5.05	10.07	9.95	14.75	14.66	20.3	20.3


Report No.: FG552956B

SPORTON INTERNATIONAL INC. Page Number : A7-4 of 39

TEL: 886-3-327-3456


FAX: 886-3-328-4978

Report Template No.: BU5-FGLTE Version 1.3




Page Number : A7-5 of 39

Report Template No.: BU5-FGLTE Version 1.3




Page Number : A7-6 of 39

Report Template No.: BU5-FGLTE Version 1.3



Page Number : A7-7 of 39

Report Template No.: BU5-FGLTE Version 1.3



Page Number : A7-8 of 39

Report Template No.: BU5-FGLTE Version 1.3

Occupied Bandwidth

Mode		LTE Band 7 : 99%OBW(MHz)										
BW	1.4MHz		3MHz		5MHz		10MHz		15MHz		20MHz	
Mod.	QPSK	16QAM	QPSK	16QAM	QPSK	16QAM	QPSK	16QAM	QPSK	16QAM	QPSK	16QAM
Lowest CH	-	-	-	-	4.5	4.5	9.05	8.99	13.46	13.46	18.3	18.38
Middle CH	-	-	-	-	4.51	4.5	9.07	9.01	13.46	13.52	18.3	18.54
Highest CH	_	-	-	-	4.5	4.51	9.07	9.07	13.52	13.49	18.38	18.42


Report No.: FG552956B

SPORTON INTERNATIONAL INC. Page Number: A7-9 of 39

TEL: 886-3-327-3456


FAX: 886-3-328-4978

Report Template No.: BU5-FGLTE Version 1.3




Page Number : A7-10 of 39

Report Template No.: BU5-FGLTE Version 1.3




Page Number : A7-11 of 39

Report Template No.: BU5-FGLTE Version 1.3



Page Number : A7-12 of 39

Report Template No.: BU5-FGLTE Version 1.3



Page Number : A7-13 of 39

Report Template No.: BU5-FGLTE Version 1.3

Conducted Band Edge


Report No.: FG552956B

SPORTON INTERNATIONAL INC. Page Number : A7-14 of 39

TEL: 886-3-327-3456


FAX: 886-3-328-4978

Report Template No.: BU5-FGLTE Version 1.3




TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : A7-15 of 39

Report Template No.: BU5-FGLTE Version 1.3




TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : A7-16 of 39

Report Template No.: BU5-FGLTE Version 1.3




Page Number : A7-17 of 39

Report Template No.: BU5-FGLTE Version 1.3




Page Number : A7-18 of 39

Report Template No.: BU5-FGLTE Version 1.3




Page Number : A7-19 of 39


Report Template No.: BU5-FGLTE Version 1.3



Page Number : A7-20 of 39


Report Template No.: BU5-FGLTE Version 1.3






Page Number : A7-22 of 39

Report Template No.: BU5-FGLTE Version 1.3




Page Number : A7-23 of 39

Report Template No.: BU5-FGLTE Version 1.3




TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : A7-24 of 39

Report Template No.: BU5-FGLTE Version 1.3




TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : A7-25 of 39

Report Template No.: BU5-FGLTE Version 1.3




Page Number : A7-26 of 39

Report Template No.: BU5-FGLTE Version 1.3




TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : A7-27 of 39


Report Template No.: BU5-FGLTE Version 1.3



Page Number : A7-28 of 39

Report Template No.: BU5-FGLTE Version 1.3





Page Number : A7-30 of 39

Report Template No.: BU5-FGLTE Version 1.3

Conducted Spurious Emission


Report No.: FG552956B

SPORTON INTERNATIONAL INC. Page Number : A7-31 of 39

TEL: 886-3-327-3456


FAX: 886-3-328-4978

Report Template No.: BU5-FGLTE Version 1.3




TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : A7-32 of 39

Report Template No.: BU5-FGLTE Version 1.3




TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : A7-33 of 39

Report Template No.: BU5-FGLTE Version 1.3




TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : A7-34 of 39

Report Template No.: BU5-FGLTE Version 1.3




TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : A7-35 of 39

Report Template No.: BU5-FGLTE Version 1.3



TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : A7-36 of 39

Report Template No.: BU5-FGLTE Version 1.3



TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : A7-37 of 39

Report Template No.: BU5-FGLTE Version 1.3

Frequency Stability

Test Conditions		LTE Band 7 (QPSK) / Middle Channel	Limit	
		BW 10MHz	Note 2.	
Temperature (°C)	Voltage (Volt)	Deviation (ppm)	Result	
50	Normal Voltage	0.0044		
40	Normal Voltage	0.0047		
30	Normal Voltage	0.0011		
20(Ref.)	Normal Voltage	0.0000		
10	Normal Voltage	0.0005		
0	Normal Voltage	0.0001		
-10	Normal Voltage	0.0023	PASS	
-20	Normal Voltage	0.0013		
-30	Normal Voltage	0.0004		
20	Maximum Voltage	0.0019		
20	Normal Voltage	0.0000		
20	Battery End Point	0.0056		

Report No.: FG552956B

Note:

- 1. Normal Voltage = 3.9V. ; Battery End Point (BEP) = 3.4 V. ; Maximum Voltage =4.35 V
- 2. Note: The frequency fundamental emissions stay within the authorized frequency block based on the frequency deviation measured is small.

SPORTON INTERNATIONAL INC. Page Number : A7-38 of 39

TEL: 886-3-327-3456

FAX: 886-3-328-4978

Report Template No.: BU5-FGLTE Version 1.3

Test Conditions		LTE Band 7 (QPSK) / Middle Channel	Limit
Tomporeture	Voltage	BW 5MHz	Within Band
Temperature (°C)	Voltage (Volt)	Frequency Offset (∆f) (Hz)	Result
50	Normal Voltage	11.1	
40	Normal Voltage	11.9	
30	Normal Voltage	2.9	
20(Ref.)	Normal Voltage	0	
10	Normal Voltage	-1.2	
0	Normal Voltage	-0.2	
-10	Normal Voltage	-5.8	PASS
-20	Normal Voltage	-3.2	
-30	Normal Voltage	0.9	
20	Maximum Voltage	-4.9	
20	Normal Voltage	0	
20	Battery End Point	14.3	

Report No.: FG552956B

|MAX(∆f)| 14.3= Hz

Frequency Stability	Frequency (MHz)	Limit Line	Result
$f_L - MAX(\Delta f) $	2500.139986	≥ 2500 MHz	DACC
f _H + MAX(△f)	2569.860014	≦ 2570 MHz	PASS

SPORTON INTERNATIONAL INC. Page Number : A7-39 of 39

TEL: 886-3-327-3456

FAX: 886-3-328-4978

Report Template No.: BU5-FGLTE Version 1.3