
Appendix C. Setup Photographs


<Radiated Emission>

Y Plane <Normal>

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZL5AP01 Page Number : C1 of C3
Report Issued Date : Jun. 19, 2018
Report Version : Rev. 01


Report No.: FG7N1019-02A

Report Template No.: BU5-FG22/24 Version 2.0




Y Plane <Battery module 3620>

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZL5AP01 Page Number : C2 of C3
Report Issued Date : Jun. 19, 2018
Report Version : Rev. 01

Report Template No.: BU5-FG22/24 Version 2.0




Y Plane <Battery module 4370>

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZL5AP01 Page Number : C3 of C3
Report Issued Date : Jun. 19, 2018
Report Version : Rev. 01

Report No.: FG7N1019-02A

Report Template No.: BU5-FG22/24 Version 2.0