

# Report No.: FR552956B

## Appendix B. Setup Photographs

## <Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40

Page Number : B1 of B2 Report Issued Date: Jul. 16, 2015 Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.0



### <Radiated Emission>

#### X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S40 Page Number : B2 of B2
Report Issued Date : Jul. 16, 2015
Report Version : Rev. 01

Report No.: FR552956B

Report Template No.: BU5-FR15CBT4.0 Version 1.0