



Report No.: FR850804-02C

Appendix E. Setup Photographs

<Conducted Emission>

Mode 2





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : E1 of E2
Report Issued Date : Jul. 06, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 2.0



<Radiated Emission>

X Plane

LF







Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : E2 of E2
Report Issued Date : Jul. 06, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 2.0

Report No.: FR850804-02C