3. Internal Photograph of EUT


Brand Name: CAT / Model Name: S61

Report No.: EP7D2711-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 13 of 30
Report Issued Date : Apr. 10, 2018
Report Version : Rev. 01


Report No.: EP7D2711-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 14 of 30
Report Issued Date : Apr. 10, 2018
Report Version : Rev. 01




Report No.: EP7D2711-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61


Page Number : 15 of 30 Report Issued Date : Apr. 10, 2018 Report Version : Rev. 01

Report No.: EP7D2711-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 16 of 30
Report Issued Date : Apr. 10, 2018
Report Version : Rev. 01

Report No.: EP7D2711-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 17 of 30
Report Issued Date : Apr. 10, 2018
Report Version : Rev. 01

Report No.: EP7D2711-02



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 18 of 30
Report Issued Date : Apr. 10, 2018
Report Version : Rev. 01


Report No.: EP7D2711-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 19 of 30
Report Issued Date : Apr. 10, 2018
Report Version : Rev. 01


Report No.: EP7D2711-02

Brand Name: CAT / Model Name: S61



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 20 of 30
Report Issued Date : Apr. 10, 2018
Report Version : Rev. 01

Report No.: EP7D2711-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 21 of 30
Report Issued Date : Apr. 10, 2018
Report Version : Rev. 01

Report No.: EP7D2711-02



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61


Page Number : 22 of 30 Report Issued Date : Apr. 10, 2018 Report Version : Rev. 01

Report No.: EP7D2711-02




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 23 of 30
Report Issued Date : Apr. 10, 2018
Report Version : Rev. 01

Report No.: EP7D2711-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61

Page Number : 24 of 30 Report Issued Date : Apr. 10, 2018 Report Version : Rev. 01




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 25 of 30
Report Issued Date : Apr. 10, 2018
Report Version : Rev. 01


Report No.: EP7D2711-02

Report No.: EP7D2711-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 26 of 30 Report Issued Date : Apr. 10, 2018 Report Version : Rev. 01

Report No.: EP7D2711-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61


Page Number Report Issued Date : Apr. 10, 2018

: 27 of 30

Report Version

: Rev. 01


Report No.: EP7D2711-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 28 of 30
Report Issued Date : Apr. 10, 2018
Report Version : Rev. 01




Report No.: EP7D2711-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 29 of 30
Report Issued Date : Apr. 10, 2018
Report Version : Rev. 01

Report No.: EP7D2711-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S61 IC: 11151A-S61 Page Number : 30 of 30 Report Issued Date : Apr. 10, 2018 Report Version : Rev. 01