3. Internal Photograph of EUT


Brand Name: CAT / Model Name: S31

Report No.: EP770420-02




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 18 of 34
Report Issued Date : Oct. 06, 2017
Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 19 of 34
Report Issued Date : Oct. 06, 2017
Report Version : Rev. 01

Report No.: EP770420-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 20 of 34
Report Issued Date : Oct. 06, 2017
Report Version : Rev. 01

Report No.: EP770420-02




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456
FAX: 886-3-328-4978
FCC ID: ZL5S31
IC: 11151A-S31

Page Number : 21 of 34
Report Issued Date : Oct. 06, 2017
Report Version : Rev. 01


Report No.: EP770420-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 22 of 34
Report Issued Date : Oct. 06, 2017
Report Version : Rev. 01




Report No.: EP770420-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 23 of 34
Report Issued Date : Oct. 06, 2017
Report Version : Rev. 01




Report No.: EP770420-02




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 24 of 34
Report Issued Date : Oct. 06, 2017
Report Version : Rev. 01



Report No.: EP770420-02




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 25 of 34
Report Issued Date : Oct. 06, 2017
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 26 of 34
Report Issued Date : Oct. 06, 2017
Report Version : Rev. 01


Report No.: EP770420-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 27 of 34
Report Issued Date : Oct. 06, 2017
Report Version : Rev. 01




Report No.: EP770420-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31

: 28 of 34 Page Number Report Issued Date : Oct. 06, 2017 : Rev. 01 Report Version

Report No.: EP770420-02




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 29 of 34
Report Issued Date : Oct. 06, 2017
Report Version : Rev. 01




Report No.: EP770420-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31

: 30 of 34 Page Number Report Issued Date : Oct. 06, 2017 : Rev. 01 Report Version






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31

: 31 of 34 Page Number Report Issued Date : Oct. 06, 2017 : Rev. 01 Report Version

Report No.: EP770420-02

Report No.: EP770420-02




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 32 of 34
Report Issued Date : Oct. 06, 2017
Report Version : Rev. 01



Report No.: EP770420-02




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31

: 33 of 34 Page Number Report Issued Date : Oct. 06, 2017 : Rev. 01 Report Version



Report No.: EP770420-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 34 of 34
Report Issued Date : Oct. 06, 2017
Report Version : Rev. 01