
3. Internal Photograph of EUT

Brand Name: CAT / Model Name: S41 / Marketing Name: S41

Report No.: EP732839-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41 Page Number : 18 of 34
Report Issued Date : Aug. 30, 2017
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41 Page Number : 19 of 34
Report Issued Date : Aug. 30, 2017
Report Version : Rev. 01




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41 Page Number : 20 of 34
Report Issued Date : Aug. 30, 2017
Report Version : Rev. 01


Report No.: EP732839-01

Brand Name: CAT / Model Name: S41 / Marketing Name: S41




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41 Page Number : 21 of 34
Report Issued Date : Aug. 30, 2017
Report Version : Rev. 01

Report No.: EP732839-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41 Page Number : 22 of 34
Report Issued Date : Aug. 30, 2017
Report Version : Rev. 01


Report No.: EP732839-01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456
FAX: 886-3-328-4978
FCC ID: ZL5S41
IC: 11151A-S41


Page Number : 23 of 34
Report Issued Date : Aug. 30, 2017
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41 Page Number : 24 of 34
Report Issued Date : Aug. 30, 2017
Report Version : Rev. 01




Report No.: EP732839-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41

: 25 of 34 Page Number Report Issued Date : Aug. 30, 2017 : Rev. 01 Report Version






SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41

: 26 of 34 Page Number Report Issued Date : Aug. 30, 2017 : Rev. 01 Report Version

Report No.: EP732839-01

Report No.: EP732839-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41 Page Number : 27 of 34
Report Issued Date : Aug. 30, 2017
Report Version : Rev. 01



Page Number


Report Version

: 28 of 34


: Rev. 01

Report Issued Date : Aug. 30, 2017

Report No.: EP732839-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41 Page Number : 29 of 34
Report Issued Date : Aug. 30, 2017
Report Version : Rev. 01

Report No.: EP732839-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41 Page Number : 30 of 34
Report Issued Date : Aug. 30, 2017
Report Version : Rev. 01







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41 Page Number : 31 of 34
Report Issued Date : Aug. 30, 2017
Report Version : Rev. 01

Report No.: EP732839-01

Brand Name: CAT / Model Name: S41 / Marketing Name: S41



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41 Page Number : 32 of 34
Report Issued Date : Aug. 30, 2017
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41 Page Number : 33 of 34 Report Issued Date : Aug. 30, 2017

Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S41 IC: 11151A-S41 Page Number : 34 of 34
Report Issued Date : Aug. 30, 2017
Report Version : Rev. 01