
Appendix C. Setup Photographs


<Radiated Emission>

Z Plane <Normal>

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZL5AP01 Page Number : C1 of C3
Report Issued Date : Jun. 19, 2018


Report No.: FG7N1019-02B

Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0


Report No.: FG7N1019-02B

Z Plane <Battery module 3620>

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZL5AP01 Page Number : C2 of C3
Report Issued Date : Jun. 19, 2018

Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0


Report No.: FG7N1019-02B

Z Plane <Battery module 4370>

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZL5AP01 Page Number : C3 of C3
Report Issued Date : Jun. 19, 2018

Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0