
Appendix C. Test Setup Photographs


<Radiated Emission>

X Plane for Part 22H

LF



HF



Sporton International (KunShan) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZL5EKTRA Page Number : C1 of C3
Report Issued Date : Apr. 14, 2017
Report Version : Rev. 01

Report No.: FG730704A


Report Template No.: BU5-FG22/24/27 Version 1.2

Y Plane for Part 24E

LF



HF



Sporton International (KunShan) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZL5EKTRA Page Number : C2 of C3
Report Issued Date : Apr. 14, 2017
Report Version : Rev. 01

Report No. : FG730704A


Report Template No.: BU5-FG22/24/27 Version 1.2

Y Plane for Part 27L

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZL5EKTRA Page Number : C3 of C3
Report Issued Date : Apr. 14, 2017
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.2

Report No. : FG730704A