

Appendix B. Setup Photographs


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5B15 Page Number : B1 of B2
Report Issued Date : Feb. 06, 2013
Report Version : Rev. 01

Report No.: FG2D2653




Report No. : FG2D2653

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5B15 Page Number : B2 of B2
Report Issued Date : Feb. 06, 2013
Report Version : Rev. 01