Appendix C. Setup Photographs


<Radiated Emission>

Y Plane

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S60 Page Number : C1 of C2
Report Issued Date : Jun. 06, 2016
Report Version : Rev. 01


Report No.: FG630110-01A

Report Template No.: BU5-FG22/24/27/90 Version 1.1


Report No. : FG630110-01A

X Plane

LF







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S60 Page Number : C2 of C2
Report Issued Date : Jun. 06, 2016
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27/90 Version 1.1