Appendix A. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S50 Page Number : A1 of A2
Report Issued Date : Aug. 19, 2014
Report Version : Rev. 01


Report No.: FR463004F

Report Template No.: BU5-FR15EWL Version 1.0


<Radiated Emission>

LF

Y Plane



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S50

Page Number : A2 of A2 Report Issued Date: Aug. 19, 2014 Report Version : Rev. 01

Report No.: FR463004F

Report Template No.: BU5-FR15EWL Version 1.0