# Appendix A. Setup Photographs

## <Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S50 Page Number : A1 of A4
Report Issued Date : Aug. 20, 2014
Report Version : Rev. 01


Report No.: FR463004E




### <Radiated Emission>

Z Plane for Mode 1~3

<LF>



#### <HF>




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S50 Page Number : A2 of A4
Report Issued Date : Aug. 20, 2014
Report Version : Rev. 01

X Plane for Mode 4

## <LF(9kHz~30MHz)>



<LF(30MHz~1000 MHz)>




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S50 Page Number : A3 of A4
Report Issued Date : Aug. 20, 2014
Report Version : Rev. 01



#### X Plane for Mode 4

#### <HF>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S50 Page Number : A4 of A4
Report Issued Date : Aug. 20, 2014
Report Version : Rev. 01