

Appendix D. Setup Photographs

<Conducted Emission>

Mode 5





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZL5AP01 Page Number : D1 of D2
Report Issued Date Jun. 19, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0


Report No.: FR7N1019-02A




<Radiated Emission>

Z Plane

LF







TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZL5AP01 Page Number : D2 of D2
Report Issued Date Jun. 19, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR7N1019-02A