
Appendix C. Setup Photographs


<Radiated Emission>

Z Plane for LTE Band 2/4/5/66

LF



HF




Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : C1 of C4
Report Issued Date : Sep. 03, 2018
Report Version : Rev. 02
Report Template No.: BU5-FGLTE Version 2.0


Report No.: FG850804-02B

Y Plane for LTE Band 7/13/25

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : C2 of C4
Report Issued Date : Sep. 03, 2018
Report Version : Rev. 02
Report Template No.: BU5-FGLTE Version 2.0


Report No. : FG850804-02B

Y Plane for LTE Band 12/26

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : C3 of C4
Report Issued Date : Sep. 03, 2018
Report Version : Rev. 02

Report No. : FG850804-02B

Report Template No.: BU5-FGLTE Version 2.0


Report No. : FG850804-02B

Y Plane for LTE Band 41

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : C4 of C4
Report Issued Date : Sep. 03, 2018
Report Version : Rev. 02
Report Template No.: BU5-FGLTE Version 2.0