


# Appendix E. Setup Photographs

## <Conducted Emission>

#### Mode 1



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S60 Page Number : E1 of E2
Report Issued Date : Jun. 06, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3


Report No.: FR630110-01B




### <Radiated Emission>

#### **Z** Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S60 Page Number : E2 of E2
Report Issued Date : Jun. 06, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3

Report No.: FR630110-01B