

Report No.: FR850804-02F

Appendix E. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : E1 of E2
Report Issued Date : Jul. 06, 2018
Report Version : Rev. 01


Report Template No.: BU5-FR15EWLB4 AC MA Version 2.0



<Radiated Emission>

Y Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : E2 of E2
Report Issued Date : Jul. 06, 2018
Report Version : Rev. 01

Report No.: FR850804-02F

Report Template No.: BU5-FR15EWLB4 AC MA Version 2.0