1. External Photograph of EUT

Brand Name: CAT / Model Name: S31

Report No.: EP770420-02




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 1 of 34
Report Issued Date : Oct. 03, 2017
Report Version : Rev. 01



Page Number : 2 of 34
Report Issued Date : Oct. 03, 2017
Report Version : Rev. 01







Page Number : 3 of 34
Report Issued Date : Oct. 03, 2017
Report Version : Rev. 01




Report No.: EP770420-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31

Page Number : 4 of 34 Report Issued Date : Oct. 03, 2017 Report Version : Rev. 01







Page Number : 5 of 34
Report Issued Date : Oct. 03, 2017
Report Version : Rev. 01



Report No.: EP770420-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31


: 6 of 34 Page Number Report Issued Date : Oct. 03, 2017

Report Version : Rev. 01






Page Number : 7 of 34
Report Issued Date : Oct. 03, 2017
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 8 of 34
Report Issued Date : Oct. 03, 2017
Report Version : Rev. 01






SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 9 of 34
Report Issued Date : Oct. 03, 2017
Report Version : Rev. 01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 10 of 34
Report Issued Date : Oct. 03, 2017
Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 11 of 34
Report Issued Date : Oct. 03, 2017
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 12 of 34
Report Issued Date : Oct. 03, 2017
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: CAT / Model Name: S31

Report No.: EP770420-02

Specification of Accessory		
IAC Adanter	Brand Name	DVE
	Model Name	DSA-10PFP-05 050150
Battery	Brand Name	APACK TECHNOLOGY CO., LTD.
	Model Name	APP00240
Earphone	Brand Name	GALIEN ELECTRON CO.,LTD
	Model Name	HF-AC04D-03 HF
ILISB Cable	Brand Name	HOTRON
	Model Name	D0005120H36CP

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 13 of 34
Report Issued Date : Oct. 03, 2017

Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 14 of 34
Report Issued Date : Oct. 03, 2017
Report Version : Rev. 01

Duran I Nicore OAT / Martel Nicore OA

Report No.: EP770420-02



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 15 of 34
Report Issued Date : Oct. 03, 2017
Report Version : Rev. 01

Report No.: EP770420-02



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 16 of 34
Report Issued Date : Oct. 03, 2017
Report Version : Rev. 01

Report No.: EP770420-02

Rechargeable Li-ion Battery

二次锂离子电池组/二次鋰離子電池組 Model/型号/型號: APP00240

Nominal voltage/标称电压/標稱電壓: 3.85Vdc

Limited charging voltage/充电限制电压/充電限制電壓: 4.4Vdc

Capacity typ./典型容量/典型容量: 4000mAh 15.4Wh Capacity min./额定容量/額定容量: 3900mAh 15.015Wh

Made in China/中国制造 /中國製造

Manufactured by APack Technology Co., LTD

制造商: 典晖科技股份有限公司/典暉科技股份有限公司 Caution: Replace with same type only. Use of another battery may

present a fire or explosion.

Please refer to user manual or follow local ordinances and/or regulations for disposal.

Do not disassemble, impact, squeeze or put into fire. If there is a serious swelling, please do not continue using.

Do not expose to temperature above 60°C/140°F. The battery is prohibited to use after soaking.

注意:用錯誤型號電池更換會有爆炸危險,務必按照說明處置 用完的電池。禁止拆解、撞擊、擠壓或投入火中。若出現嚴重 鼓脹,請勿繼續使用。請勿至於高溫環境中。電池浸水後禁止 使用。

注意:用错误型号电池更换会有爆炸危险,务必按照说明处置用完的电池。禁止拆解、撞击、挤压或投入火中。若出现严重鼓胀,请勿继续使用。请勿置于高温环境中。电池浸水后禁止使用。

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S31 IC: 11151A-S31 Page Number : 17 of 34
Report Issued Date : Oct. 03, 2017

Report Version : Rev. 01