Internal Photograph of EUT 3.

Brand Name: CAT; Model Name: S48c

Report No.: EP850804-02



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C

: 12 of 34 Page Number Report Issued Date : Jul. 10, 2018

Report Version : Rev. 01




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 13 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C






TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 15 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01

Report No.: EP850804-02




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 16 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01






TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 17 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 18 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 19 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01

Report No.: EP850804-02




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 20 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01

Report No.: EP850804-02




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 21 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01

Report No.: EP850804-02




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 22 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01

Report No.: EP850804-02




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 23 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01

Report No.: EP850804-02




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 24 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01

Report No.: EP850804-02




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 25 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 26 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01






TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 27 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 28 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01






TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 29 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01





TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 30 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01






TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 31 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01





TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 32 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01





TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 33 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01





TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: ZL5S48C Page Number : 34 of 34
Report Issued Date : Jul. 10, 2018
Report Version : Rev. 01