
## Appendix A. Setup Photographs


## <Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S30 Page Number : 1 of 2
Report Issued Date : Aug. 11, 2015
Report Version : Rev. 01


Report Template No.: BU5-FG22/24/27 Version 1.2

Report No.: FG570160A

## Report No. : FG570160A

## **Z** Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZL5S30 Page Number : 2 of 2
Report Issued Date : Aug. 11, 2015
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.2