


Report No.: FR730704F

## Appendix D. Setup Photographs

## <Conducted Emission> Mode 1





Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZL5EKTRA

: D1 of D2 Page Number Report Issued Date : Apr. 14, 2017 Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC Version 2.0




FCC Test Report Report No.: FR730704F

## <Radiated Emission>

Y Plane

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZL5EKTRA Page Number : D2 of D2
Report Issued Date : Apr. 14, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC Version 2.0