
CC Test Report No.:FC730704

Appendix A. Setup Photographs

<Conducted Emission>

Mode 4





Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZL5EKTRA Page Number : A1 of A4
Report Issued Date : Apr. 14, 2017
Report Version : Rev. 01

Report No. :FC730704

Mode 6





Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZL5EKTRA Page Number : A2 of A4
Report Issued Date : Apr. 14, 2017
Report Version : Rev. 01

C Test Report No. :FC730704


<Radiated Emission>

Mode 2

LF



HF




Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZL5EKTRA Page Number : A3 of A4
Report Issued Date : Apr. 14, 2017
Report Version : Rev. 01


Report No. :FC730704

Mode 6

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZL5EKTRA Page Number : A4 of A4
Report Issued Date : Apr. 14, 2017
Report Version : Rev. 01