
Internal Photos FLIR-T5590 camera.



Figur 1 FLIR-T5590



Figur 2 Plastic cover remowed.



Figur 3 Radio board PIWI4




Figur 4 Radio board PIWI4, bottom side.



Figur 5 PIWI4 and PIVF4 board removed.



Figur 6 Radiometric unit removed.



Figur 7 Display unit taken apart.



Figur 8 Computer board.