
2. Internal Photograph of EUT

Brand Name: FIBOCOM; Model Name: L831-EA

Report No.: EP531804




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: ZMOL831 Page Number : 3 of 6

Report Issued Date : Jun. 29, 2015 Report Version : Rev. 01

Brand Name: FIBOCOM; Model Name: L831-EA

Report No.: EP531804




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: ZMOL831 Page Number : 4 of 6

Report Issued Date : Jun. 29, 2015 Report Version : Rev. 01

Brand Name: FIBOCOM; Model Name: L831-EA

Report No.: EP531804



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: ZMOL831 Page Number : 5 of 6

Report Issued Date : Jun. 29, 2015 Report Version : Rev. 01



Brand Name: FIBOCOM; Model Name: L831-EA S **GPS Antenna Port <Rx>** B8 FIBOCOM L831-EA SN: T3B2FJ0110 IMEI:866807020001799 FCC ID:ZMOL831 C € 0700 Port <Tx/Rx> 30

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: ZMOL831

: 6 of 6 Page Number

Report Issued Date: Jun. 29, 2015 Report Version : Rev. 01

Report No.: EP531804