






TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B2 OF B18
ISSUED DATE : Apr. 14, 2014









TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B3 OF B18
ISSUED DATE : Apr. 14, 2014










SPORTON International Inc.
















TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B6 OF B18
ISSUED DATE : Apr. 14, 2014









TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B7 OF B18
ISSUED DATE : Apr. 14, 2014



















TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B9 OF B18
ISSUED DATE : Apr. 14, 2014

















TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B11 OF B18























Eytro B5

Lytro B5

Lytro

**Report No. : EP422631** 




SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B14 OF B18











FCC Test Report No.: EP422631







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B16 OF B18










TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B17 OF B18





TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B18 OF B18