






TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B2 OF B24
ISSUED DATE : Jul. 7, 2014



0 90 80 70 60 50 40

Report No. : EP452053


30 20




TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B3 OF B24

















































SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B8 OF B24











TEL: 886-3-327-3456 FAX: 886-3-327-0973








































TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B13 OF B24































TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B16 OF B24




















TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B18 OF B24









TEL: 886-3-327-3456 FAX: 886-3-327-0973 **Report No. : EP452053**







