

Report No. : FA452053

Appendix D. SAR Test Setup Photos



Front Face, Test Separation 0 cm

SPORTON INTERNATIONAL INC. Page No. : A1 of A1
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973