




Photographs of EUT

For EUT 1 (Internal Ant.)















Report No.: 612817










Report No.: 612817









Report No.: 612817







Report No.: 612817



SPORTON International Inc.

TEL : 886-3-327-3456


FAX : 886-3-327-0973

PAGE NUMBER : 10 of 25

ISSUED DATE : Apr. 29, 2016



Report No.: 612817




SPORTON International Inc.

TEL : 886-3-327-3456

FAX : 886-3-327-0973



PAGE NUMBER : 11 of 25

ISSUED DATE : Apr. 29, 2016





Report No.: 612817



SPORTON International Inc.

TEL : 886-3-327-3456


FAX : 886-3-327-0973

PAGE NUMBER : 13 of 25

ISSUED DATE : Apr. 29, 2016



Report No.: 612817



SPORTON International Inc.

TEL : 886-3-327-3456



FAX : 886-3-327-0973

PAGE NUMBER : 14 of 25

ISSUED DATE : Apr. 29, 2016





Report No.: 612817







Report No.: 612817







SPURTON LAB.

Report No.: 612817





Report No.: 612817



SPORTON International Inc.



TEL : 886-3-327-3456


FAX : 886-3-327-0973

PAGE NUMBER : 18 of 25

ISSUED DATE : Apr. 29, 2016










SPURTON LAB.

Report No.: 612817



For EUT 2 (External Ant.)

