


Appendix D. Product Photos





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZQ6-99PW020046R Page Number : D1 of D1
Report Issued Date : Jul. 14, 2011
Report Version : Rev. 01

Report No. : FA151919




Report No.: FA151919

Appendix E. Test Setup Photos



Direct Laptop Plug-in for USB Configuration 1 (Horizontal Up with Phantom 5 mm Gap)



USB Cable Plug-in for USB Configuration 2 (Horizontal Down with Phantom 5 mm Gap)



Direct Laptop Plug-in USB Configuration 3 (Vertical Front with Phantom 5 mm Gap)



USB Cable Plug-in for USB Configuration 4 (Vertical Back with Phantom 5 mm Gap)



USB Cable Plug-in for USB Configuration 5 (Tip Mode with Phantom 5 mm Gap)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZQ6-99PW020046R Page Number : E1 of E1
Report Issued Date : Jul. 14, 2011
Report Version : Rev. 01