


Report No. : FR310925

Appendix A. TEST PHOTOS

Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A1 of A4 TEL: 886-3-327-3456 Report Version : Rev. 01



Test Photos Report No. : FR310925




SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01



Test Photos Report No. : FR310925

2 Photographs of Radiated Emissions Test Configuration For radiated emission below 1GHz



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A3 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01

Test Photos Report No. : FR310925

For radiated emission above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A4 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01