

Setup Photographs

<Conducted Emission>

Mode 1



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZQANC31 Page Number : 1 of 3
Report Issued Date : Apr. 19, 2017
Report Version : Rev. 01

Report No.: FR630207-02C

Report Template No.: BU5-FR15CWL AC MA Version 1.3



Report No.: FR630207-02C



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZQANC31 Page Number : 2 of 3
Report Issued Date : Apr. 19, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL AC MA Version 1.3




Report No.: FR630207-02C

<Radiated Emission>

X back Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZQANC31 Page Number : 3 of 3
Report Issued Date : Apr. 19, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL AC MA Version 1.3