

Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZQANC41 Page Number : 1 of 3
Report Issued Date : Sep. 08, 2017

: Rev. 02

Report No.: FR6N0107-01D

Report Template No.: BU5-FR15EWL AC MA Version 2.0

Report Version





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZQANC41 Page Number : 2 of 3
Report Issued Date : Sep. 08, 2017
Report Version : Rev. 02

Report No.: FR6N0107-01D


Report Template No.: BU5-FR15EWL AC MA Version 2.0



<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZQANC41 Page Number : 3 of 3

Report No.: FR6N0107-01D

Report Issued Date : Sep. 08, 2017
Report Version : Rev. 02

Report Template No.: BU5-FR15EWL AC MA Version 2.0