Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : 1 of 6


TEL: 886-3-327-3456 Report Version : Rev. 01

FCC TEST REPORT

1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : 2 of 6

TEL: 886-3-327-3456 Report Version : Rev. 01



SIDE VIEW


SPORTON INTERNATIONAL INC. Page No. : 3 of 6

TEL: 886-3-327-3456 Report Version : Rev. 01

FCC TEST REPORT Report No.: FR272106AC

2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : 4 of 6


TEL: 886-3-327-3456 Report Version : Rev. 01

FCC TEST REPORT Report No.: FR272106AC

For radiated emissions 30MHz~1GHz



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : 5 of 6


TEL: 886-3-327-3456 Report Version : Rev. 01

FCC TEST REPORT Report No.: FR272106AC

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : 6 of 6

TEL: 886-3-327-3456 Report Version : Rev. 01